


TOOLING SCHEDULER					- X
CNC-1	CNC-2	CNC-3	CNC-4	CNC-5	CNC-6
123X456	126X457	123X458	123W459	222X123	222U123
123X456	126X457	123X458	123W459	222X123	222U123
123X456	126X457	123X458	123W459	222X123	222U123
123X456	126X457	123X458	123W459	222X123	222U123
123X456	126X457	123X458	123W459		
123X456	126X457	123X458			

Click on Ref# will open another window.



- A. List of operations needs to be performed.
- B. Design print will be opened in a popup window on Landscape.
- C. Setup sheet will be opened in a popup window on Portrait and its scrollable.
- D. .CNC file will be downloaded on a computer.
- D. It'll open final simulation image from surfcam.